

ChargeLine

Release notes

Firmware release 1.9.2

2026 Q3

Introduction

Dear customers and ChargeLine partners,

We are pleased to provide you with this document containing important information and instructions regarding Firmware Update 1.9.2 for our charging stations. This release includes new features and bug fixes to improve functionality, usability, and performance. We recommend sharing this valuable information with the relevant stakeholders within your organization.

New Features in Firmware Update 1.9.2

The latest firmware update introduces several new features that expand the functionality of the charger and simplify its operation. Here are the highlights:

- **Xemex Smart Connect – improved support through a direct Ethernet connection**

Previously, when connecting an Xemex Smart Connect via a direct Ethernet connection, the IP address had to be configured manually. This is now done automatically when Xemex Smart Connect is selected as the metering source.

- **Bug fixes and improvements**

An issue was fixed where the connection to a HomeWizard P1 meter could remain permanently disabled after a temporary outage. For example, the charging current could remain limited to 16 A or the solar power limitation could be removed until the charger was restarted.

In addition, an issue was fixed that prevented socket charging stations with “Keep cable locked” enabled from starting a charging session after a restart.

THE INFORMATION IN THIS DOCUMENT IS FOR INFORMATIVE PURPOSES ONLY, IS PROVIDED AS IS, AND MAY BE SUBJECTED TO CHANGE WITHOUT NOTICE.

While reasonable efforts are undertaken to ensure that this information is correct, we cannot guarantee that the information provided is completely free from inaccuracies. We are not liable for possible inaccuracies or completeness of information.

Reach out to the ChargeLine account managers for inquiries.

